

STATINTL

BTATINTL

9 June 1964

Subject:

STATINTL Electronic Transistorized Recording Accumulating Counters

STATINTL

Gentlemen:

STATINTL

is pleased to submit the enclosed proposal and its associated cost quotation in response to the request and specification outlined in code 822, file 3900. This proposal is for modification of a unit which is presently being fabricated on the and consequent STATINTL expeditious approval of this change is required, to minimize adverse affects on the delivery of the modified unit. Present in-house schedules on thf \$TATINTLunit and the proposed delivery schedule of the counter manufacturer indicate that the schedule for delivery of a modified unit does not have to be changed in order to incorporate the modification. This is based on receipt of award within thirty (30) days of this date, 9 June 1964, and on performance of the counter manufacturer to his proposed schedule. As noted on the attached proposal estimate sheet, the firm fixed price effect this change STATINTL

STATINTL STATINTL

STATINTL

increase. is

STATINTL

Please refer to supplemental agreement No. 1 to the referenced contract. The effect on the target cost noted in paragraph (a) is an increase of The effect on the target profit is an increase of the contract should change as follows:

> Target: Cost Target: Profit Contingency (cost) Ceiling Price

There is no effect on the fixed price items in the contract. Should you require any additional information relative to the above, please contact the undersigned.

Very truly yours,

STATINTL

STATINTL

STATINTL

STATINTL

ELECTRONIC TRANSISTORIZED
RECORDING ACCUMULATING COUNTERS

STATINTL

Approved For Release 2002/01/02 : CIA-RDP78B047474502100090054-14

ELECTRONIC TRANSISTORIZED RECORDING ACCUMULATING COUNTERS

This proposal is submitted in response to and conforms with specifications as outlined in Code 822 File 3900.

The purpose of this product improvement is to provide an encoding measurement system with electronic transistorized recording accumulating counters.


Basically, the system will consist of a rack (Figure 1), in accordance with the Block Diagram (Figure 2). The system operation will be as follows:

Encoders attached to the X and Y lead screws will feed pulses equivalent to 2 1/2 microns at the film plane into solid state up-down counters. Upon operator demand, this count information together with the three (3) digit event counter data will be processed, converted, coded and recorded on an eight (8) level punch tape in a BCD code. A 100 hole patch board will provide program information flexibility. Convenient remote controls will permit the operator to zero reset all counters, as well as automatically record all data.

DESCRIPTION OF EQUIPMENT AND WORK STATEMENT

- Install (4) 1000 count per revolution encoders, Data Tech Magnetic Incrosyn type. 1.5 diameter to eliminate rework of base frame and carriage castings. 1000 count/rev. will provide a least bit measurement resolution of 2 1/2 microns when decoding 2 1/2 milimeter pitch screws. Encoder count rate of 20 KC is expected to be more than adequate for 10,000 bit per second rate equivalent to 1 inch/second carriage travel.
- 2) (4) 6 decade bi-directional high speed counters employing transistorized plug in decade boards and mounted for maximum heat dissipation together with accessability for easy maintenance. True negative and positive + indication is provided on nixie tube numeric displays, (one for each coordinate axis).
- 3) Event Counter 3 decade, solid state counters with visual readout and reset-preset capabilities.
- 4) Input Output sequencors, with decoder logic, punch driver, converter, start-stop print logic and remote control provisions with all necessary interconnecting cables.
- 5) Patch board with patch wires and interconnecting wiring (50 input to 50 hole output), see Figure 2. This is in accordance with the above referenced specifications.
- 6) Tape punch (Talley or Friden). Print format will be compatible with 8 channel Dura-BCD code.
- 7) Console to house the above items 2, 3, 4, and 5. This console contains a blower for cooling, and contains racks on slides to allow accessibility for maintenance.

8) An interlock circuit will be provided so that power to the X and Y drive is removed while readout to the tape punch is in progress.



STATINTL

F14. 1


Approved For Release 2002/01/02 : CIA-RDP78B04747A002100090054-READ OUT SYSTEM

PATCH BOARD USED TO CHANGE PRINT OUT SEQUENCE

	1 2 3 4 5 6 7 8 9 10	
	11 12 13 14 15 16 17 14 19 20	
(21 22 23 24 25 26 27 28 27 30 31 32 33 24 25 26 37 38 39 40	
	41 42 48 40 41 44 47 48 49 50	4 .
	\$3016176+STOP + 8 8 8 8 6 6 - XI COORD	WATE (6)
λ	6 STOP = 6 6 6 6 6 6 870A YI (±6)	•
X2(+6)	± 6 6 6 6 6 6 6 38A ± 6 7	
· Con ·	6 6 6 6 6 5 BA / /2 (t 6)	mar a sintenda
	TAB CREND FUD OF C	YCLE INTERLOCA BIT
	123 45678 PRINTOUT-RECOR	FORMAT
	3 DIGIT: IDENTIFICATION	FROM 3 2/6/7;
		_
	O > STOP > SIGN PLUS. MINUS	1 01617
	0	
	6 DIGITS XI COORDINATES	1 DIGITS
	6 DIGITS XI COORDINATES	(
		101617
	516N +6 DIGHT	\sim
	Y, COOKDINATES	1 6 7314175
		12/9/7
	570p SIGN + 60/6/75	7 781517
	X2 COORDINATES	3 /3/3//3
•	STOP	101617
	STOP SIGN + 6 2/5/75	3.7316,7
	Y2 COOLDINATES	
•	STOP	131911
		,
	· · · · · · · · · · · · · · · · · · ·	2 3/6/15
	GARRIAGE RET))
		enggangengengerggag, mga santrika sarta dakkiyartingnyggiga manamati terugengi gamanagangi gantrikatingnyggiga
	LSPROCKET	38 DKILS
		 -

STATINTL

Approved For Release 2002/01/02 : CIA-RDP78B04747A002100090054-1



STATINTL

F19. 3

BLOCK DIAGRAM
Approved For Release 2002/01/02: CIA-RDP78B04747A0020099999999892 EMENT-READOUT
SYSTEM